SOVRINTENDENZA TAL-PATRIMONJU KULTURALI

$N_{ational}\ I_{nventory}\ {of}\ the\ C_{ultural}\ P_{roperty}\ of\ the\ M_{altese}\ I_{slands}$

NICPMI Inv. No. 1703

Date of Publication 28 June 2013

| SUPERINTENDENCE OF CULTURAL HERITAGE | | | 2 | | 20 junie 20 | ,10 |
|--------------------------------------|--|---------------|-------------------|---------------------|-------------|------|
| SUPERINTENDENCE OF CULTURAL HERITAGE | | | | | | |
| Property Name | Remains of Ramla Entrenchment - Gozo | | | | | |
| Address | Ramla Bay, Gozo | | | | | |
| Town Name | Nadur | Toponyı | n | Local Council Nadur | | |
| Property Owner | Government | Managing Bod | y | | | |
| Guardianship Deed | | | | | | |
| | | | | | | |
| Period | Modern (18th Century) | | | | | |
| Phase | Early Modern: Knights of St John (1700-1798) | | | | | |
| 6 1, 1, 1, | Historical | | Cultural Heritage | | | |
| Cultural Heritage Type & Value | Architectural | | Property Value | Outstandi | ng | |
| | Assessment | | | | | |
| Property Function | Fortification | | Conservation Area | | | |
| | 1 | | | | | |
| Outline Description | Entrenchment wal | l remains | | | | |
| | | | | | | |
| Property Description | Sparse remains of entrenchment wall built in the petra a secco manner. Originally | | | | | |
| | this cut across the beach from near Belancourt Battery to the other side of the bay. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| Scheduled by MEPA | Yes Degree | of Protection | Grade 1 G.N. No | . 7 | G.N. Date | 1995 |
| Scheduled by MEI A | res Degree | orrotection | Grade 1 G.N. No | . / | G.N. Date | 1993 |
| | | | | | | |
| | | | | | | |
| Recommended | | | | | | |
| Bibliography | | | | | | |
| | | | | | | |



